Material Inspection - Detailed
Date: 2/2/2022 12:00:00 AM
Plant: Plant 1 - Chicago Plant
Part: 1-Aluminum Bracket
Operator: 7b0f1f3f-0a8a-3b7e-a0c1-8c7d9e4f2a1b
Machine: 9e4d2f8a-3b7c-5d1e-a9f0-2c6b8e1d4f7a
Inspection Method: Visual Inspection
Defects Found: Surface Scratch, Dimensional Out of Tolerance
Notes: Operator noted slight variation in bracket thickness near mounting hole. Dimensional tolerance ±0.005 in. Out of tolerance by approx 0.0012 in.