Material Supplier: CABLEY
Part Number: 1000-1
Date: 2022-08-24
Rev: 2022-08-24 2022
Warning: Prolonged flexible flex life may cause conductor, insulation and jacket to crack/split/fracture, resulting in exposed conductors and shorts. Consult with Cabley for advice on flex life.